



School District of Philadelphia Office of Environmental Management & Services 440 North Broad Street Philadelphia, PA 19130 (215) 400-4750

Transmitted via Electronic Mail

Ms. Kyla L. Townsend-McIntyre U.S. Environmental Protection Agency, Region III Pesticides/Asbestos Programs and Enforcement Branch (3WC32) 1650 Arch Street Philadelphia, PA 19103-2029

Re:

Self Disclosure Agreement - AHERA Constitution High School ULCS #2670

Dear Ms. Townsend-McIntyre

As part of the School District of Philadelphia agreement, effective March 9, 2007 and amended January 18, 2008 with the United States Environmental Protection Agency (EPA), this letter is intended to transmit and certify the Corrective Action Plan (CAP) for the Constitution High School.

This Disclosure Report was written in accordance with the above noted agreement and the "Incentives for Self-Policing: Discovery, Disclosure, Correction and Prevention of Violations," 65 Federal Register 19618 (4/11/00) (the Policy).

As the Responsible Official, I hereby certify that the attached report entitled *CAP – Constitution High School ULCS #2670* submitted to EPA is true, accurate and complete in the form set forth in 40 C.F.R. § 270.11(d).

If you have any questions or comments please feel free to contact me or Ms. Elizabeth Gutman, Esq.

Sincerely.

Francine Locke, MS

Director, Environmental Management & Services

SELF AUDIT DISCLOSURE REPORT CORRECTIVE ACTION PLAN

Updated as of: May 15, 2008

Facility Name: Constitution High School #2670

Facility Address: 18 S. 7th Street, Philadelphia, PA 19106

Date of Audit: 04/04/08 Date CAP due to EPA: 6/3/08

Finding Number	Regulatory Citation	Finding	Corrective Action	Corrective Action Status(include date when closed)	Preventative Measure	Preventative Measures Status (include date when closed)	Extension Filed (Y/N)	Exhibit Reference	Approximate Cost to Close Finding	Potential Reduction of Pollutants *INCLUDE AMT OF OIL
			ASBESTOS HA	ZARD EMERGENCY RESPONSE ACT (AH	IERA) PROGRAM 40 CFR § 763 Subpart	C				
I	(40 CFR § 763.93(a)(2))	An initial management plan in dated January 2007. This location initally opened as a school in September 2007. For buildings obtained after October 12, 1988 the LEA must submit the plan to the DEP Bureau of Air Quality	Submit a copy of the latest Reinspection Report to the DEP Bureau of Air Quality.	Closed 5/9/08 - A copy of the latest reinspection report was submitted to the following: Commonwealth of Pennsylvania DEP Bureau of Air Quality Attn: Randy Koppenhaver 400 Market Street P.O. Box 8468 Harrisburg, PA 17101-8468	Maintain accurate up-to-date information regarding buildings that are planned for lease or purchase. Ensure that the DEP Bureau of Air Quality receives a copy of the management plan for all new locations		N	1	\$400	Recordkeeping violation
2	(40 CFR § 763.85(b)(1)(vii))	The regulations require that the 3 Year Reinspections records be updated within 30 days of the inspection. The most recent Reinspection Report is dated January 2007 and was available for review at the central file and the school building, however it was recently printed/distributed and was not completed within the required 30 day time frame from the inspection date in January 2007.	The 3 Year Reinspection records must be updated within 30 days of the actual inspection. This is a historical finding.	Historical finding. Corrective Action can not be completed.	Implement and track the Reinspection date in a compliance calendar so that the 30 day update can be tracked by both the school and personnel in the central office for the next 3 Year Reinspection in 2009.	established and implemented so that the 30 day update can be tracked by the	N	2	N/A	Recordkeeping violation
					<u> </u>					

School District of Philadelphia Asbestos Hazard Emergency Response Act (AHERA) Compliance Audit

Principal Interview Form

The School District of Philadelphia (School District) and the U.S. Environmental Protection Agency, Region III (EPA) entered into a Self-Audit/Self Disclosure Agreement. The purpose of the agreement is to gauge the School District's compliance with the Asbestos Hazard Emergency Response Act (AHERA) requirements for your school/ facility.

The School District obtained the services of URS Corporation (URS) to conduct the AHERA environmental compliance audit. The audit will focus on the compliance of general information, inspections and reinspections, response actions, operations and maintenance, periodic surveillance, and notifications. This document acknowledges that all environmental documents relevant to the building asbestos management plan have been made available to URS at the time of the audit.

School/ Facility	
	Constitution High School #2670
Address:	18 S. 7th Street
Date of Audit:	4/4/08
School Principa	<u>l:</u>

Sign Name: The A D

Print Name: I LICMAS K VACIOSON

Date: 4/4/08

8516	U.S. Postal CERTIFIED (Domestic Mail Communication of the Communication) I Only	VIAI ; No I	L _T	_M R uranα	e Co	verage			
339	OFF		C		A	le au	U	S	Second Second Second TITE	
016 5	Postage Certified Fee	\$					ರ	-/9	108	/
) 000k	Return Reclept Fee (Endorsement Required)						P	ostma Here	rk	
2260	Restricted Delivery Fee (Endorsement Required) Total Postage & Fees	\$				-				
7003	Serito Kandij Koppe		are	· /	· į	<u> </u>	e Bi	rea	w	£
ارب م	Street, Apt. No.; or PO Box No.	ζύζ	e 8	¥			400	M	VEC	7.07
	PS Form 3800, June 2002		18G		A		7 (S)	e for i	7 ©	ons

Certified Mail Provides: A mailing receipt

PS Form 3800, June 2002 (Reverse)

- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:
■ Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®. Certified Mail is not available for any class of International mail.

- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider insured or Registered Mail.
- valuables, please consider insured or Registered Mail.

 For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the Receipt (PS Form 3811) to the article and add applicable postage to cover the sendorse mallpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mallpiece with the endorsement "Restricted Delivery".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry. Internet access to delivery information is not available on mail addressed to APOs and FPOs.

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. Article Addressed to: 	A. Signature X
Athn Randy Koppenhaver DEP Bureau of Air Quality 400 Market St P.O.Box 8468 Harrisburg, PA 17101-8468	Constitution High
P.O.Box 8468 Harrisburg, PA 17101-8468	3. Se vice Type
	4. Restricted Delivery? (Extra Fee)
2. Article Number 7003 2260 (Transfer from service lab)	000b 5339 851b
PS Form 3811, February 2004 Domestic Retu	rn Receipt 102595-02-M-1540

.





School District of Philadelphia Office of Environmental Management & Services 440 North Broad Street Philadelphia, PA 19130 (215) 400-4750

May 7, 2008

Attn: Randy Koppenhaver DEP Bureau of Air Quality 400 Market Street P.O. Box 8468 Harrisburg, PA 17101-8468

Re: Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance

Mr. Koppenhaver

I am submitting herewith the asbestos management plan for the School District of Philadelphia as required by the terms of the Asbestos Hazard Emergency Response Act of 1986. This plan was developed with the assistance of Synertech Incorporated and Batta Environmental Incorporated. The inspection was conducted by Synertech Incorporated.

The Asbestos Coordinator for the School District of Philadelphia is

Mr. Jerry Junod 440 North Broad Street, Room 3053 Philadelphia, PA 19130 215-400-6738

All records pertaining to the School District's AHERA Compliance Program are maintained at the above designated location.

If you have any questions or comments, please feel free to contact Francine Locke at 215-400-4750 or Jerry Junod at 215 400-6738.

Sincerely,

Francine Locke, MS

Director, Environmental Management & Services

SCHOOL DISTRICT OF PHILADELPHIA

AHERA

THREE YEAR REINSPECTION VI

Constitution High School

ULCS# 2670

7TH and Market Streets Philadelphia, Pennsylvania

January, 2007

Conducted By:

Batta Environmental Associates, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
Kleinfelder East, Incorporated
Synertech Incorporated
USA Environmental Management, Incorporated

Prepared By:

School District of Philadelphia
Batta Environmental Associates, Incorporated
Synertech Incorporated

SCHOOL DISTRICT OF PHILADELPHIA EDUCATION CENTER

440 NORTH BROAD STREET, 3RD FLOOR PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT & SERVICES

PHONE - (215) 400-4750

January, 2008

TO:

All Principals

All Building Engineers

FROM:

Francine Locke, Manager

Environmental Management & Services

SUBJECT:

AHERA Reinspection Report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA), the attached report is submitted to you. The law requires that this report be kept in the offices of the principal and the building engineer. It cannot be removed from these locations. All asbestos reports must be available to the public upon request.

Patrick A. Henwood, Director

Office of Capital Programs

Francine Locke, Manager

Office of Environmental Management

and Services

AHERA THREE YEAR REINSPECTION VI TABLE OF CONTENTS

- Transmittal letter
- Table of Contents
- Asbestos Coordinator Accreditation Information Statement
- Executive Summary

Section I Report of Reinspection

- A. Introduction
- B. Management Planner's Accreditation Statement
- C. Original Management Plan Information
- D. Post-Management Plan Activities and Changes
- E. Three Year Reinspection Overview
- F. Response Actions and Prioritization

Section II Reinspection Data

- A. Introduction
- B. Building Inspector's Accreditation Statement
- C. Reinspection Form Key
- D. Reinspection Forms
 - 1. Homogeneous Area Reports
 - 2. Specific Location Logs

Executive Summary

The AHERA Three Year Reinspection VI of the Constitution High School, has been completed and the report of the reinspection submitted to the School District of Philadelphia. The reinspection was conducted as a joint project of Batta Environmental Associates, Incorporated, Environmental Testing Consultants, LLC, G & C Environmental Services, Incorporated, Kleinfelder East, Incorporated, Synertech Incorporated and USA Environmental Management, Incorporated. This reinspection was conducted on January 29, 2007 by Melissa Kendzior, Building Inspector of Environmental Testing Consultants, LLC.

The information contained in the report of the reinspection was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the Management Plan and from the Three Year Reinspection of the school. This reinspection report was prepared by Jeffrey M. Kuntz, Management Planner of Batta Environmental Associates, Incorporated.

The following Asbestos Containing Building Materials (ACBMs), which were identified in the original Management Plan or in the 1992, 1995, 1998, 2001 or 2004 AHERA Three Year Reinspection reports, were inspected for this project:

No Applicable Material

The following Asbestos Containing Building Materials (ACBMs), were identified during this AHERA Three Year Reinspection and were not included in the original Management Plan of 1988 or 1989 or in the subsequent three year reinspection reports:

• Floor Tile VAT 12" x 12" located in the Basement and on the First, Second, Third, Fourth and Fifth Floors, was identified and ASSUMED to contain asbestos. Damage to this material was noted in the Basement. No damage to this material was noted on the First, Second, Third, Fourth or Fifth Floors. ***(Note: All Floor Tile must be bulk sampled before any renovation work is performed, unless previously sampled).

Section I Report of Reinspection

- A. Introduction
- B. Management Planner's Accreditation Statement
- C. Original Management Plan Information
- D. Post-Management Plan Activities and Changes
- E. Three Year Reinspection Overview
- F. Response Action Prioritization

Report of Reinspection

Introduction

The Three Year Reinspection VI was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must reinspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This reinspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

The reinspection of the Constitution High School, was performed on January 29, 2007 by Melissa Kendzior, Building Inspector of Environmental Testing Consultants, LLC. The report of the reinspection was prepared by Jeffrey M. Kuntz, Management Planner of Batta Environmental Associates, Incorporated.

Accreditation information for the Management Planner is located in *Section I.B.* of this report. Accreditation information for the Building Inspector is located in *Section II.A.* of this report.

During the reinspection of each School District of Philadelphia facility, the Management Plan for that facility was reviewed. Information from the conclusions section of that report is included in Section I.C. of this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, was reviewed during the reinspection. Information on those activities is included in Section I.D. of this report.

Section I - B

MANAGEMENT PLANNER ACCREDITATION STATEMENT

The under-signed Management Planner has reviewed the reinspection data, developed prioritized response actions, and made recommendations for the subject school/facility addressed in this AHERA Three Year Reinspection Report. The scope of this report is based upon the information contained in the Asbestos Hazard Emergency Response Act of 1986, and other Federal regulations and EPA publications. EPA personnel reviewed the report format prior to its finalization.

Management Planner:

Jeffrey M. Kuntz

Employer:

Batta Environmental Associates, Inc.

Telephone Number:

(302) 737-3376

Accreditation Agency:

Central Delaware Training Academy, Inc.

Accreditation Number:

025952

CENTRAL DELAWARE TRAINING ACADEMY, INC.

JEFFREY M. KUNTZ

has successfully completed EPA APPROVED

AHERA MANAGEMENT PLANNER REFRESHER TRAINING

COURSE LENGTH 4 HOURS

April 17th, two thousand-seven

DAVID T. STANLEY, PRESIDEN

RONALD S. HERCHA, VICE PRESIDENT

EXAM DATE: 041707

CDTA

P.O. BOX 1344

(302) 677-1534

DOVER, DE 19903-1344

EXPIRE DATE: 041708

ID NUMBER CMP070417-0049

Section I - C

Original Management Plan Information

Not Available

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at the Constitution High School, is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

PERIODIC (SIX MONTH) SURVEILLANCE

Month/Year

June, 2006

On June 29, 2006, a Six Month Surveillance of ACM was conducted at the Franklin Institute Science and Leadership Academy. The following areas were reported to contain damaged ACM:

LOCATION

TYPE OF MATERIAL

**Note: Building undergoing major interior renovation at time of visit.

OPERATIONS AND MAINTENANCE

Month/Year

No Applicable data

ABATEMENT

Month/Year

No Applicable Data

SAMPLING AND ANALYSIS

Month/Year

No Applicable Data

Three Year Reinspection VI Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan and in the 1992, 1995, 1998, 2001 or 2004 Three Year Reinspection reports were inspected for the AHERA Three Year Reinspection VI, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the reinspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three Year Reinspection. The results of the AHERA Three Year Reinspection VI are tabulated in the homogeneous area reports located in Section II of this report.

Response Action Prioritization

The AHERA Three Year Reinspection VI included the determination of response actions for the Asbestos Containing Building Materials (ACBMs) observed at the subject school/facility. The ACBMs were also given prioritization rankings.

The **Response Action (RA)** rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions:

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- 3. Enclose
- 4. Encapsulate
- 5. Remove
- **6.** Partial Removal and Establish O&M Program

a. High Priority Response

The homogeneous area has been scheduled for abatement or other response action.

b. Medium Priority Response

The homogeneous area will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

c. Low Priority Response

The homogeneous area will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

d. On-Going Response/Operations and Maintenance

The homogeneous area does not require abatement at present, and should be included in the facility's on-going operations and maintenance program.

The response actions and prioritization rankings for the subject school/facility, as determined in the Three Year AHERA Reinspection VI, are as follows:

Priority

Homogeneous Area/Response Action

Low Priority Response

HA#

2650/01/0B/FF

Material:

Floor Tile VAT 12" x 12"

Location:

Basement

RA#

<u>6/C</u>

On-Going Response/ Operations and Maintenance

HA#

2650/01/01/AA

Material:

Floor Tile VAT 12" x 12"

Location:

First Floor

RA#

<u>1/D</u>

HA#

2650/01/02/BB

Material:

Floor Tile VAT 12" x 12"

Location:

Second Floor

RA#

<u>1/D</u>

HA#

2650/01/03/CC

Material:

Floor Tile VAT 12" x 12"

Location:

Third Floor

RA#

<u>1/D</u>

HA# 2

2650/01/04/DD

Material:

Floor Tile VAT 12" x 12"

Location:

Fourth Floor

RA#

<u>1/D</u>

HA#

2650/01/05/EE

Material:

Floor Tile VAT 12" x 12"

Location:

Fifth Floor

RA#

<u>1/D</u>

Section II Reinspection Data

- A. Introduction
- B. Building Inspector's Accreditation Statement
- C. Reinspection Form Key
- D. Reinspection Forms
 - 1. Homogeneous Area Information Report
 - 2. Specific Location Logs

Section II - A

Reinspection Data

Introduction

The following information documents the Three Year Reinspection VI of the subject school/facility. The homogeneous area reports were produced using the building inspector's field data on the facility. Key to the homogeneous area report is located immediately prior to that portion of the report.

Section II - B

BUILDING INSPECTOR ACCREDITATION STATEMENT

The undersigned building inspector has applied the scope and procedures of the AHERA Three Year Reinspection to the subject school/facility addressed in this report. The inspection techniques utilized for this inspection are based on those recommended in EPA guidelines.

Building Inspector:

Melissa M. Kendzior

Employer:

Environmental Testing Consultants, LLC

Telephone Number:

(856) 482-1311

Accreditation Agency:

Access Training Services, Inc.

Accreditation Number:

032234

Signature

Certificate of Completion

Melissa Kendzior

for successfully completing the prescribed course of study in

EPA/AHERA/Pennsylvania Asbestos **Building Inspector Refresher Course**

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC. 706 West Maple Avenue, Merchantville, NJ 08109

(856) 665-3449

3/16/06

Course Date

N/A Exam Date

3/16/07

Expiration Date

Not Provided

Social Security Number

ACC-0306-6-043

Certificate Number

Training Director

Section II - C (page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR REINSPECTION VI

REINSPECTION FORM KEY

ITEM	DEFI	NITIC	ON										
ULCS#		Is the ULCS# for the school. Designates the specific building/building area within the school. Designates the floor or level within the building/building area. Designates the homogeneous material within that floor or level. Item D may be a number or a letter. Thermal System Surfacing System Miscellaneous											
HOMOGENEOUS AREA ID#	school	l/facilit											
	A. B. C. D. Note:	Desig Desig	gnates the specific building/building area within the school gnates the floor or level within the building/building area. gnates the homogeneous material within that floor or level.										
SYSTEM AFFECTED	A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building are D. Designates the homogeneous material within that floor or le Note: Item D may be a number or a letter. Corresponds to the AHERA system for classifying materials. T : Thermal System S : Surfacing System												
	S	: :	Surfacing System										
ITEM AFFECTED	Is a des	scriptic	on of the homogeneous material.										
ORIGINAL INSPECTION DATA													
AMOUNT OF MATERIAL/ UNIT			naterial, and measuring unit. : Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet										

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR REINSPECTION VI

REINSPECTION FORM KEY

ITEM	DEFINITION									
CND Condition	Corre	sponds t	o AHERA condition rating for materials.							
	0	:	No Damage							
	1	:	Damage							
	2	:	Significant Damage							
DP Damage Potential	Corres	sponds to	o the AHERA material assessment system.							
	1	:	Potential for Damage							
	2	:	Potential for Significant Damage							
ASMD Assumed Asbestos			at a material was not sampled for asbestos content ginal Management Plan inspection.							
RA	This co		ds to the AHERA system of response action rating for							
Response										
Action	1	:	Establish O&M Program							
	2	:	Repair and Establish O&M Program							
	3	:	Enclose							
	4 5	•	Encapsulate							
	6 ,	:	Remove Partial Removal and Establish O&M Program							
CHANGES	eightee		scribes changes to the homogeneous material in the since the original AHERA inspection. The abbreviations ow.							
	RMVE	•	: Removed							
	ENCL		: Enclosed							
	ENCP		: Encapsulated							
	DMGI)	: Damaged							
	SMPL		: Sampled							
	MTRL		: Material							
	RPRD		: Repaired							
	N/L		: None Located							
	RPLCI)	: Replaced							

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR REINSPECTION VI

REINSPECTION FORM KEY

T	Т	E	A	л
1	ĸ	Ľ	17	1

DEFINITION

THREE YEAR REINSPECTION DATA

This section contains the information obtained from the Three Year Reinspection VI. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.

DMGD AMT Amount Damaged

This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.

NF Newly Friable

This section identifies materials in the original Management Plan which have since become friable.

RA Response Action

This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.

- 1. Establish O&M Program
- 2. Repair and Establish O&M Program
- 3. Enclose
- 4. Encapsulate
- 5. Remove
- **6.** Partial Removal and Establish O&M Program

a. High Priority Response

The homogeneous material has been scheduled for abatement or other response action.

b. Medium Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.

c. Low Priority Response

The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.

SCHOOL DISTRICT OF PHILADELPHIA AHERA THREE YEAR REINSPECTION VI

REINSPECTION FORM KEY

ITEM

DEFINITION

d. On-Going Response/Operations and Maintenance
The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

The information presented in the changes section has been compiled from a variety of sources, including the Reinspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

SPECIFIC LOCATION LOG

This section gives information, including damage amount and location, for a specific homogeneous material on a room by room basis and follows the reinspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three Year Reinspections. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three Year Reinspection VI evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Homogenous Area Information Report By ULCS Location Three Year Reinspection

Building Inspector:

Melissa Kendzior

Number:

032234

Management Planner: Jeffrey M. Kuntz

Number:

025952

|--|

Homo Area ID: 2670 / 01 / 01 / AA	ORIGINAL INSPECTION DATA					CHANGES	THREE YR. REINSPECTION DATA					' A
	Amount of						Amount of		DMGD			
System Affected: Miscellaneous	MTRL/Unit	CND	DP	ASMD	RA		MTRL/Unit	CND	AMT	DP	NF	RA
Item Affected: Floor Tile VAT 12" x 12"						MTRL	1929 SF	0	0	1	No	1/D

Homo Area ID: 2670 / 01 / 02 / BB	ORIGINAL	L INSI	PECT	ION DA	TA	CHANGES	THREE YR. REINSPECTION DATA					'A
	Amount of						Amount of		DMGD			
System Affected: Miscellaneous	MTRL/Unit	CND	DP	ASMD	RA		MTRL/Unit	CND	AMT	DP	NF	RA
Item Affected: Floor Tile VAT 12" x 12"						MTRL	6957 SF	0	0	1	No	1/D

Homo Area ID: 2670 / 01 / 03 / CC	ORIGINAL INSPECTION DATA					CHANGES	THREE YR. REINSPECTION DATA					[A
	Amount of						Amount of		DMGD			
System Affected: Miscellaneous	MTRL/Unit	CND	DP	ASMD	RA		MTRL/Unit	CND	AMT	DP	NF	RA
Item Affected: Floor Tile VAT 12" x 12"		L	 			MTRL	2704 SF	0	0	1	No	1/D

Homo Area ID: 2670 / 01 / 04 / DD	ORIGINAL INSPECTION DATA					CHANGES	THREE YR. REINSPECTION DATA					$\Gamma \mathbf{A}$
	Amount of						Amount of		DMGD			
System Affected: Miscellaneous	MTRL/Unit	CND	DP	ASMD	RA		MTRL/Unit	CND	AMT	DP	NF	RA
Item Affected: Floor Tile VAT 12" x 12"				L		MTRL	10374 SF	_ 0	0	1	No	1/D

Homo Area ID: 2670 / 01 / 05 / EE	ORIGINAL INSPECTION DATA			CHANGES	THREE Y	R. RE	INSPE	CTIO	N DAT	`A		
System Affected: Miscellaneous	Amount of MTRL/Unit	CND	DP	ASMD	RA		Amount of MTRL/Unit	CND	DMGD AMT	DP	NF	RA
Item Affected: Floor Tile VAT 12" x 12"						MTRL	8951 SF	0	0	1	No	1/D

Homogenous Area Information Report By ULCS Location Three Year Reinspection

Building Inspector:

Melissa Kendzior

No

6/C

Number:

032234

Management Planner: Jeffrey M. Kuntz

2 SF

Number:

7896 SF

DMGD

025952

Homo Area ID: 2670 / 01 / 0B / FF	ORIGINA	L INS	PECT	TON DA	TA	CHANGES	THREE Y	R. RE	INSPE	CTIO	N DAT	ĪA
System Affected: Miscellaneous	Amount of MTRL/Unit	CND	DP	ASMD	RA		Amount of MTRL/Unit	CND	DMGD AMT	DP	NF	RA
						MTRL						

Item Affected: Floor Tile VAT 12" x 12"

01/29/07

Reinspection Date:

School Name:	Constitution High School	ULCS #	: 2670
Homogenous ID #:	2670 / 01 / 01 / AA	Date:	01 / 29 / 07
Homogenous ID Des	scription: Floor Tile VAT 12" x	k 12"	

Location / Room #	Amount of Material	Amount Damaged	Description / Notes
First Floor Hallway Foyer Elevator Area Room 121 End Rm. near Rest Rm.	1023 SF	0	Black
Foyer Elevator Area	420 SF	0	White
Room 121 End Rm. near Rest Rm.	270 SF	0	White
Room 121A in Room 121	216 SF	0	White
	1		
			·
	<u> </u>		

School Name: Constitution	High School	ULCS #: 2670
Homogenous ID #: 2670 / 01 / 02	2 / BB	Date: 01 / 29 / 07
Homogenous ID Description:	Floor Tile VAT 12"	x 12"

Location / Room #	Amount of Material	Amount Damaged	Description / Notes
Faculty Work Room 206	280 SF	0	White
Mechanical Room	88 SF	0	White
Electrical Room	50 SF	0	Black
Room 205	750 SF	0	White
Room 204	750 SF	0	White
Room 203	750 SF	0	White
Room 202	960 SF	0	White
Room 216 Storage	360 SF	0	White
Hallway-Rm. 202-201Main Office	595 SF	0	Black - Hall
Room 201 Main Office-206	550 SF	0	Black – Hall (Faculty Work Rm.)
Rm. 206 Faculty Work Rm 205	536SF	0	Black - Hall
Room 205-202 Hall	468 SF	0	Black
Foyer Area 202 & 203	456 SF	0	White
204 – 207 IMC Hall	368 SF	0	Black
		-	
			·
1			
	:		

School Name: Constitution	n High School	ULCS #	*: 2670
Homogenous ID #: 2670 / 01 /	03 / CC	Date:	01 / 29 / 07
Homogenous ID Description:	Floor Tile VAT 1	2" x 12"	

Location / Room #	Amount of Material	Amount Damaged	Description / Notes
Room 304	0	0	Carpeted
Room 304 Health Suite	300 SF	0	White – Nurses Office
Room 304A Exam Room	215 SF	0	White
Room 305 Guidance	0	0	Carpeted
Room 306	300 SF	0	White
Book Room #1(Unspecified #)	270 SF	0	White
Book Room #1(Unspecified #) Book Room #2(Unspecified #)	216 SF	0	White
Hallway	1023 SF	0	Black
Foyer Elevator Area	380 SF	0	White

School Name: Constitution High School	ULCS #: 2670
Homogenous ID #: 2670 / 01 / 04 / DD	Date: 01/29/07
Homogenous ID Description: Floor Tile VAT 12	2" x 12"

Location / Room #	Amount of Material	Amount Damaged	Description / Notes
Kitchen Teachers lounge	360 SF	0	White
Room 402 Right of Kitchen	940 SF	0	White
Unspecified Room Sink	648 SF	0	White
Room 420 B & A	1270 SF	0	White
Room 420A Lab Room	407 SF	0	White - Office Storage
Room 405	720 SF	0	White
Room 404	720 SF	0	White
Room 403	725 SF	0	Black
Room 402 Social Studies	920 SF	0	White
Hall 402-Kit. / Teachers Lounge	500 SF	0	Black
Hall Kitchen – Unspecified Rm.	256 SF	0	Black
Room 420B-420A Hallway	200 SF	0	Black
Room 420A - 405	712 SF	0	Black – Rest Room Area
Hall 405 - 402	468 SF	0	Black
Foyer Area near 402 & 403	456 SF	0	White
Hall 404 – 420B	616 SF	0	Black
Mechanical & Electrical Room	336 SF	0	Black
Janitors Closet	84 SF	0	Black

School Name:	Constitution High School	ULCS #: 2670	
Homogenous ID #:	2670 / 01 / 05 / EE	Date: 01/29/07	
Homogenous ID De	escription: Floor Tile VAT	12" x 12"	

Location / Room #	Amount of Material	Amount Damaged	Description / Notes
Room 506 & 507	1260 SF	0	White – Science Room
Room 507 Lab / Office	407 SF	0	White - Storage
Room 508, 504, 503, 505	1140 SF	0	White-Four Rooms Combined as 1
Room 503A Sink	270 SF	0	White
Room 504A	234 SF	0	White
Hall 503 - 511	895 SF	0	Black
Elevator Area	350 SF	0	Black
Room 511 – 507 Hall	700 SF	0	Black
Hall 507 - 506	280 SF	0	Black
506-Elevator Hall	545 SF	0	Black
522 – 501 Hall	306 SF	0	Black
501 Door Exit Hall	270 SF	0	Black
Room 501 Art Room	870 SF	0	White
Room 502	580 SF	0	White
Room 522	684 SF	0	White
Electrical Room	160 SF	0	Black
		·	
·			
			· · · · · · · · · · · · · · · · · · ·

School Name: Constitution High School	ool ULCS #: 2670	
Homogenous ID #: 2670 / 01 / 0B / FF	Date: 01/29/07	
Homogenous ID Description: Floor Tile VAT 12" x 12"		

Location / Room #	Amount of Material	Amount Damaged	Description / Notes
Dining Area	2655 SF	0	Green & White
Two Halls-(R.R. & Elevator Sides)	450 SF	0	Green
Unspecified Room Material Area	280 SF	0	White
Janitors Storage Room	112 SF	0	White
Cafeteria Area	2604 SF	0	Green & White
Cafeteria Storage Area	100 SF	0	White
Kitchen	900 SF	0	White
Kitchen Storage	195 SF	0	White
Hallway Btwn. Kit. & Dining Area	120 SF	0	White
Stairwell	50 SF	0	White
Kitchen Office	82 SF	0	White
Hall to Sub-Basement	153 SF	2 SF	Tan
Electric Room	110 SF	0	Green
Electric Hallway	50 SF	0	Green
Stairwell to Electric Room	35 SF	0	Green

Asbestos Hazard Emergency Response Act (AHERA) **Environmental Compliance Audit Cross Reference Table**

In response to the AHERA Environmental Compliance Audit, a Cross Reference Table has been prepared for inclusion into the AHERA Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table

Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 2
Annual Notification	Pages 3 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Reinspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR) Demolition Directive Procedure	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Re-inspection Report. 2 hour awareness training records for all Building Engineers Custodian Assistants and maintenance personnel. 40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.
Response Actions (monthly mailings if applicable)	The original documents are on file at the School District's Environmental Library. Copies of the original are mailed to the School's Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.

SCHOOL DISTRICT OF PHILADELPHIA ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course Drexel University- Asbestos Management Planner Course January 9-11, 1989 24 Hours January 12-13, 1989 16 Hours

Annual Building Inspector Refreshers

Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

1990 through 2007 4 Hours

Annual Building Management Planner Refreshers

Drexel University Criterion Laboratories, Inc 1990 through 1994 4 Hours

Manager, City of Philadelphia Asbestos Control Program

Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)

Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.

Philadelphia Environmental Task Force

Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Pubic Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.

Gerald F. Junod Asbestos Designated Person Assistant Environmental Manager Office of Environmental Management and Services

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry our response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT

Gerald F. Junod Asbestos Designated Person Assistant Environmental Manager Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES /

PHONE (215)-400-4750

September 4, 2007

TO:

All Principals

All Building Administrators

All Parents/Guardians

FROM:

Patrick A. Henwood, Senior Vice President

Office of Capital Programs

Francine Locke, Manager

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.93(g)(4) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Enclosed please find a copy of the Notification Letter and a Parents' Signature form informing them of the availability of this information for review. Each member of the school staff is also required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution. The signed Parent forms are to be returned to the school and retained with the existing AHERA Management Plan, Three Year Reinspection reports, etc., in a central location by the Principal.

Note: The AHERA Three Year Reinspection reports, in colored binders; Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe penalties (\$) if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's/Main Office for the primary data and the Building Engineer's Office for the secondary duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Patrick A. Henwood Senior Vice President

Office of Capital Programs

Francine Locke, Manager

Office of Environmental Management

and Services

OFFICIAL NOTICE

PLEASE POST

TO:

Principals

Building Administrators
Building Engineers
Building Occupants
Parents/Guardians

FROM:

Patrick A. Henwood, Senior Vice President

Office of Capital Programs

Francine Locke, Manager

Office of Environmental Management and Services

SUBJECT:

Annual Notice: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, part III, in Schools: Final Rule and Notice, 763.84 states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including periodic re-inspections and surveillance activities. The School District as the local education agency retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place
- 2) Inform Building Occupants
- 3) A copy of the notification sent to Parents/Guardians (along with the Notification Form to be returned to school)

4) Insert a copy in the latest AHERA Three Year Reinspection report (red binder) in your office or facility

Patrick A. Henwood, Senior Vice President

Office of Capital Programs

Francine Locke, Manager

Office of Environmental Management

and Services

Annual EPA Notification Form

September 4, 2007

TO:	All Parents or Guardians	
FROM:	Francine Locke, Manager Francine Locke, Management and Services	
•		•
of the Asbe	to acknowledge receipt of the Annual EPA Notification stos Hazard Emergency Response Act (AHERA) Man reports for review.	
	all be signed and returned to school for filing with the Alated school staff.	HERA Management Plan, etc.,
Thank you fo	r your timely response.	· · · · · · · · · · · · · · · · · · ·
Ctu danta Nam	· · · (DDIN/T)	
Students Ivan	ne (PRINT)	
School (PRIN	VT)	
Grade Level (PRINT)	
		. *
Parent/Guardia	in (PRINT)	·
•		
Parent/Guardia	n Signature	

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Six Month Surveillance Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a management plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first bi-annual inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's environmental library and filed.

Education Center 440 North Broad Street Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA Three Year Reinspection Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a management plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- Subsequent three year reinspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The inspectors state of accreditation and license number is required.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's environmental library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street Philadelphia, PA 19130 (215) 400-4750

School District of Philadelphia Asbestos Management Program

TABLE OF CONTENTS

	Definitions	Page 10
1	. Introduction	Page 11
2	. Summary of Asbestos Management Plan	J
	. Asbestos Management Plan Execution	Page 12
	a. General Execution	· ·
4		
	a. Asbestos Management Plan Execution	
5	. Responsibilities	
	a. OEMS	
	b. Asbestos Worker/Supervisor "A-TEAM"	Page 13
	c. Asbestos Designated Person	
	d. Supervisor or Project Manager (Capital, Maintenance	e & Facilities)
	e. Employee Capital	Page 14
	f. Employee Maintenance	J
	g. Employee Facilities and Custodial	
6.	Requirements	Page 15
	a. Employee Exposure Monitoring	•
	b. Employee Notification	
	c. Observation of Monitoring	
	d. Training Program	
	e. Access of Information	
	f. Record Keeping	
7.	AHERA O&M Plan	Page 16
	a. Controls	
	b. Work Order System	
	c. Regulated Areas	
	d. Warning Signs	
	e. Warning Labels	
8.	O&M Response Actions	Page 17
	a. Facility Maintenance Isolation of Area	
	b. Unlikely Contact with ACM/PACM	
	c. Accidental Disturbance of ACM/PACM	
	d. Planned Disturbance of ACM/PACM	
	e. Miscellaneous ACM/PACM	Page 18
	f. Vinyl Asbestos Floor Tile	
	g. Mastic / Adhesives	
	h. Woven Vibration Dampers	
	i. Other Work Practices	
	j. Fiber Release Episodes	
9.	References and Resources	Page 19

DEFINITIONS/ACRONYMS

ACM/PACM Asbestos Containing Material /Potential Asbestos Containing

Material

AHERA Asbestos Hazard Emergency Response Act

AIR FORM Asbestos Inspection Report Form

Amended Water Water to which a surfactant (soap) has been added.

AMP Asbestos Management Program/Asbestos Management Plan

Asbestos Designated Person Individual assigned by the district to oversee asbestos related

issues

Asbestos Regulated Area Location that is posted as an asbestos work area in which only

approved and accredited personnel are permitted to enter.

AST Asbestos Support Team involving approved and accredited school

district tradespersons personnel that are school district person

A-TEAM School District of Philadelphia asbestos workers

CIP Capital Improvement Program

Consultant Asbestos consulting firm hired by the District

Demolition Directive Memorandum - August 4, 2006 from Patrick Henwood

EPA Environmental Protection Agency

In House Personnel School District of Philadelphia asbestos workers

LEA Local Education Agency

O&M Operations and Maintenance

OEMS Office of Environmental Management and Services

OSHA Occupational Safety and Health Administration

PEL Permissible Exposure Limit

PSD or SDP Philadelphia School District/School District of Philadelphia

PSIT Philadelphia School Improvement Team

STEL Short Term Excursion Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers;
- (2) Asbestos waste is handled and disposed of properly;
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters;
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents;
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations.

Requirements outlined in this manual are mandatory in nature where the word "SHALL" is used and are advisory in nature where the word "SHOULD" is used.

2) Summary of Asbestos Management Program

The School District of Philadelphia's Asbestos Management Program was established to meet the requirements of Federal, State and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3) Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health & Welfare Fund.

4) Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5) Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage is required.

- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.
- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor-"A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - (a) Attend an initial Worker/Supervisor Asbestos Course;
 - (b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - (c) Undergo an annual Asbestos Medical Evaluation;
 - (d) Undergo an annual Respirator Medical Clearance;
 - (e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - (a) warning labels/signage
 - (b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/ Renovation Notification form
 - (c) Asbestos Inspection Reports (AIR) form (where required)
 - (d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing materials may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

(1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspections Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Manager Responsibilities;
- (4) Keep the department chairperson or director informed of any actions proposed or taken regarding the Asbestos Management Program.
- (5) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

c) Employee - Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.).

d) Employee - Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment

e) Employee - Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend required Asbestos Awareness training program within 60 days of employment.

2) Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation of Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- o health effects of asbestos
- o locations of ACM and PACM in the building/facility
- o recognition of ACM and PACM damage and deterioration
- o requirements of the OSHA 1910.1001 standard relating to maintenance
- o proper response to fiber release episodes
- o procedure to be followed to isolate areas affected by fiber releases

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7) AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i) Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii) Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short-term exposure limit (STEL) (Per OSHA determined to be 1.0 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designated and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii) Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv) Warning Labels

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8) O &M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by an approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance & facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning techniques. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed directly to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9) REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- Philadelphia Air Management Services Asbestos Control Unit
 http://www.phila.gov/health/units/ams/Asbestos/asbestos.html
- Pennsylvania Asbestos Occupations, Accreditation and Certification Act
 http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=
- United States Environmental Protection Agency Asbestos Home Page http://www.epa.gov/asbestos/
- Occupational Health and Safety Administration (OSHA) Asbestos Home Page

http://www.osha.gov/SLTC/asbestos/

At W				A BOWLE
(~@ ∵_	&	714	۶,

City of Philadelphia - Department of Public Health Public Health Services - Air Management Services Asbestos Control Unit - 321 University Av., 19104

Asbestos Inspection Report

Use Only	Date Received L&I:	Date Received AMS:
Office U	Date Inspected:	Inspector #

1. Name of Building:		Phone #			
2. Name of Building Owner: S 440	School District of Philadelphia North Broad Street, Philadelphi	ia, PA 19130	Phone # 215-400-	750	
3. Name of Licensed Investiga	itor:	License #	Phon	#	
4. Name of Certified Lab:	ATTINICATION OF THE PROPERTY AND ASSESSMENT OF THE PROPERTY OF	License #	Phone	:#	
5. Scope of Work: (include all	locations)		~~		
			\ Y		
Yang Mataria	T V (I is Delow)				
-	l Present? Yes (List Below)				
i. List Asbestos Containing M	laterial (ACM) located in the pl	la. ad renovation/dem			
5. List Asbestos Containing M hen repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
5. List Asbestos Containing M	laterial (ACM) located in the pl	la sed renovation/dem) must label all ACM	that may be left in the Amount	work area. Page	e 1 of
5. List Asbestos Containing M hen repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
6. List Asbestos Containing M hen repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
6. List Asbestos Containing M hen repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
6. List Asbestos Containing M hen repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
5. List Asbestos Containing M hen repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
6. List Asbestos Containing M then repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	e 1 of
6. List Asbestos Containing M then repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) mast label all ACM t	that may be left in the Amount	work area. Page Condition	Action
6. List Asbestos Containing M then repaired or removed prior t	laterial (ACM) located in the plate renovation. Yet Investigator	la ed renovation/dem) must label all ACM (Type (Code 1) Squ	that may be left in the Amount	work area. Page Condition (Code 2)	Action

irements of section X of the Asbestos Control Regulation (ACR) have been met. The building owner has been notified of the ACR requirements and given a copy of this report. If the inspection has revealed ACM which will be disturbed by the proposed work or if it has revealed ACM in bad condition, the building owner has been notified to remove or repair the ACM in accordance with the ACR prior to renovation or demolition activity.

Signature of Licensed Asbestos Investigator: Date: Signature of Building Owner: Date:



City of Philadelphia - Department of Public Health Public Health Services - Air Management Services Asbestos Control Unit - 321 University Av., 19104 Asbestos Inspection Report School District of Philadelphia projects ONLY

age 2 of Project Name	Project Name: Project No.						
continued ist Asbestos Containing Materia paired or removed prior to renov	al (ACM) located	d in the plann	ned renovation/den				isted and the
	.			4	nount	Conditio.	Action
Location	Des	escription	Type (Code 1)	Square Ft.	Linear Ft.	(Code 2)	(Code 3)
					\		
					X	X	
					X		
. List all locations inspected the	at do NOT have	asbestos cor	ntaining material	ent:	,		
Location	T.o.	cation		scation		Tantio	
Location	1.00	ation		Cation		Location	<u>a</u>
							
Tiet all hamageneous material	1 in this	s ool:	,				
List all homogeneous material	is present in this.	3001:					
ASBESTOS CONTA	INING NATER	LLS		NON-AS	BESTOS MAT	ERIALS	
							
				· · · · · · · · · · · · · · · · · · ·			
. Caution l. bels affixed to all A	CM ?	Yes	☐ No				
<i>,</i>	·		· .				
411 contracto	ous' amplayees	- implied	in the demolitio	TO THOMOUND	tion activity		
			in ine aemoiiiio is to this Asbesto			MUSI	

OFFICE OF CAPITAL PROGRAMS

440 NORTH BROAD STREET, 3RD ELOOR PHILADELPHIA, PENNSYLVANIA 19130-4015

TELEPHONE (213) 400-4730

FAX (215) 400-4731

August 4, 2006

TO:

All Project Management Personne

FROM:

Patrick Henwood, Director

Office of Capital Programs

SUBJECT: Construction Projects

Effective immediately, if it is necessary to demolish or open a wall, ceiling or floor as part of a construction project, it is now required that a special assessment be made by the PSIT environmental consultant, prior to commencement. The purpose of this new control is to prevent construction workers from unknowingly being exposed to asbestos containing materials.

The procedure will be as follows: the Construction Manager (CM) will provide the Project Manager (PM) with a two week look-ahead indicating exact locations of surfaces that will need to be deniclished or altered. If possible, the CM will clearly mark/tabel the offected surfaces and/or items. The PM will then notify the Environmental Department who will send a City of Philadelphia licensed investigator to inspect and test the areas. The work may not proceed unless and until the investigator provides a report that clears the area.

Additionally, please ensure that, for all projects, a copy of the latest AHERA report, the appropriate Asbestos Inspection Report and all MSDS are available and posted in conspicuous locations. If environmental concerns are expressed to the CM by construction workers and can not be resolved, please have the CM contact you and the Environmental Department at (215) 400-4730 as soon as possible.

Thank you for your cooperation in this matter.

C. Fred Farling Len Dillinger, PE Joel Jackson Joe Joseph Francine Locke Gene Becker Vince Pagliaro

OFFICE OF CAPITAL PROGRAMS 440 NORTH BROAD STREET, SUITE 373 PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 4, 2007

TO:

All Principals

All Building Administrators/Occupants

All Parents/Guardians

FROM:

Patrick A. Henwood, Senior Vice President

Office of Capital Programs

Mgr Francine Locke, Director

Office of Environmental Management and Services

SUBJECT:

Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.93(g)(4) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Enclosed please find a copy of the Notification Letter and a Parents' Signature form informing them of the availability of this information for review. Each member of the school staff, temporary workers and/or contractors, are also required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution. The signed Parent forms are to be returned to the school and retained with the existing AHERA Management Plan, Three Year Reinspection reports, etc., in a central location by the Principal.

Note: The AHERA Three Year Reinspection reports, in colored binders; Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe penalties (\$) if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's/Main Office for the primary data and the Building Engineer's Office for the secondary duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.

Patrick A. Henwood

Senior Vice President

Office of Capital Programs

Francine Locke, Director

Office of Environmental Management

and Services



School District of Philadelphia **OFFICIAL NOTICE**

PLEASE POST

File #204 September 4, 2007

TO:

Principals

Building Administrators Building Engineers Building Occupants Parents/Guardians

FROM:

Patrick A. Henwood, Senior Vice President

Office of Capital Programs

Francine Locke, Director

Office of Environmental Management and Services

SUBJECT:

Annual Notice: Asbestos Hazard Emergency Response Act

The Federal Register published on October 30, 1987, part III, in Schools: Final Rule and Notice, 763.84 states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including periodic re-inspections and surveillance activities. The School District as the local education agency retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- Post in a Public Place 1)
- 2) Inform Building Occupants
- A copy of the notification sent to Parents/Guardians (along with the Notification to be returned to school) Form

4) Insert a copy in the latest AHERA Three Year Reinspection report (red binder) in office or facility.

your

Patrick A. Henwood, Senior Vice President

Office of Capital Programs

Francine Locke, Director

Office of Environmental Management

and Services

Annual EPA Notification Form

All Parents or Guardians

TO:

September 4, 2007

FROM:	Francine Locke, Director Environmental Management an	nd Services	•
availability o	to acknowledge receipt of the fifth the Asbestos Hazard Emergerear Reinspection reports for review	ncy Response Act (AHERA	•
Plan, etc.,	all be signed and returned to seated school staff.	chool for filing with the A	HERA Management
Thank you for	r your timely response.		
Students Nam	ne (PRINT)		
School (PRIN	(TV		
Grade Level ((PRINT)		
Parent/Guardia	an (PRINT)		
Parent/Guardia	an Signature		